

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
1	BRS	L1	0	"railroad frog" same plug	USPAT; EPO; JPO; DERWEN T	2004/06/15 08:18			0
2	BRS	L2	0	railroad same frog same plug	USPAT; EPO; JPO; DERWEN T	2004/06/15 08:19			0
3	BRS	L3	0	railroad same frog same plugs	USPAT; EPO; JPO; DERWEN T	2004/06/15 08:19			0
4	BRS	L4	4	railroad same frog same (coupling or junction)	USPAT; EPO; JPO; DERWEN T	2004/06/15 08:24			0
5	BRS	L5	130	246/454	USPAT; EPO; JPO; DERWEN T	2004/06/15 08:27			0
6	BRS	L6	32	246/455	USPAT; EPO; JPO; DERWEN T	2004/06/15 09:11			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
7	BRS	L7	48	246/456	USPAT; EPO; JPO; DERWENT	2004/06/15 09:19			0
8	BRS	L8	97	246/457	USPAT; EPO; JPO; DERWENT	2004/06/15 09:34			0
9	BRS	L9	67	246/458	USPAT; EPO; JPO; DERWENT	2004/06/15 09:49			0
10	BRS	L10	155	246/460	USPAT; EPO; JPO; DERWENT	2004/06/15 09:58			0
11	BRS	L11	60	246/461	USPAT; EPO; JPO; DERWENT	2004/06/15 10:17			0
12	BRS	L12	158	246/468	USPAT; EPO; JPO; DERWENT	2004/06/15 10:26			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
13	BRS	L13	72	246/382	USPAT; EPO; JPO; DERWENT	2004/06/15 10:27			0
14	BRS	L14	95	246/383	USPAT; EPO; JPO; DERWENT	2004/06/15 10:27			0
15	BRS	L15	58	246/384	USPAT; EPO; JPO; DERWENT	2004/06/15 10:27			0
16	IS&R	L16	172	(246/382, 383, 384).CCLS.	USPAT; EPO; JPO; DERWENT	2004/06/15 10:31			0
17	BRS	L17	74	246/274	USPAT; EPO; JPO; DERWENT	2004/06/15 10:32			0
18	BRS	L18	79	246/275	USPAT; EPO; JPO; DERWENT	2004/06/15 10:32			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
19	BRS	L19	116	246/276	USPAT; EPO; JPO; DERWENT	2004/06/15 10:32			0
20	BRS	L20	15	246/265	USPAT; EPO; JPO; DERWENT	2004/06/15 10:32			0
21	BRS	L21	156	246/252	USPAT; EPO; JPO; DERWENT	2004/06/15 10:32			0
22	IS&R	L22	379	(246/274,275,265,252,276).C CLS.	USPAT; EPO; JPO; DERWENT	2004/06/15 10:33			0